

# AeroHoff

Inspection Services, Inc.

(760) 567-4123

Oceanside, CA

## Piper 28 Spar CRACK EDDY CURRENT INSPECTION per Piper Service Bulletin 3145



Aerohoff comes to your facility/hanger to perform the on-site eddy current inspection of the Piper Wing Spar per SB 3145. We have performed over 65 carry-thru-spar inspections since last year, finding a few aircraft with crack-like indications.


Call or email us today to schedule your Piper Wing Spar eddy current inspection. Four fasteners pre-removed is all that is needed. Major discounts for multiple aircraft within the same day.



Right Forward  
Outboard Hole w  
Crack in Wing Spar  
Protruding Aft



Wing Removed from  
Aircraft. Crack  
verified with surface  
eddy current and 10X  
Visual



Eddy Current  
Indication of 0.030"  
x 0.030" reference  
Notch for  
Calibration



Eddy Current  
Indication of Crack in  
Actual Wing Spar

We are an FAA Certified Mobile Repair Station and can return the aircraft to service.

[www.aerohoff.com](http://www.aerohoff.com) / [www.eddycurrentguys.com](http://www.eddycurrentguys.com)

[sales@aerohoff.com](mailto:sales@aerohoff.com) / 760-567-4123